

Parts Bulletin



PB25-021 8/18/25

Subject: Cord Assy Changed

Applicable Model: MFS 40/50/60A(W): 004715BE, MFS 75/90/100/115/140A(W): 005079BE

Please revise the original Parts Catalog and/or the Service Manual to conform to the change(s) shown herein.


Reason(s) for Improvement / Change						
☐	Reinforcement	☐	Durability	☒	Dimension / Shape	☒
☐	Serviceability	☐	Weight Saving	☐	Material Change	☐
☐	Corrosion Resistance	☐	Drivability	☐	Parts Commonality	☐
Other						
Comment: Diagnostic connector changed						

〈Differentiation〉

Please identify by part number or shape.


MFS 40/50/60A(W)

No.1,2 CORD ASSY




1,2

Diagnostic Connector




MFS 75/90/100/115/140A(W)

No.3 CORD ASSY



3

Diagnostic Connector



Interchangeability	A		B		C		D		Interchangeable as a set
	Part	Engine	Part	Engine	Part	Engine	Part	Engine	
	Old	Old	Old	Old	Old	Old	Old	Old	
	New	New	New	New	New	New	New	New	

Parts Bulletin



PB25-021 8/18/25

〈Parts〉

No.	Part Name	Previous Part Number	New Part Number	Qty.	Interchange-ability	Applicable Models
1	CORD ASSY	3KY-76110-4	3KY-76110-5	1	D	MFS 40/50A(W)
2	CORD ASSY	3UR-76110-0	3UR-76110-1	1	D	MFS 60A(W)
3	CORD ASSY	3UG-76110-0	3UG-76110-1	1	D	MFS 75/90/100/115/140A(W)
4	DIAGNOSTIC TOOL KIT	3SS-72920-1	3SS-72920-2	1	D	MFS 40/50/60A(W) MFS 75/90/100/115/140A(W)
5	EXTENSION CORD	-	3UG-76112-0	1	-	MFS 75/90/100/115/140A(W)

• DIAGNOSTIC TOOL KIT

Due to a recent change in the code assy, a dedicated extension code is now required when using the diagnostic tool kit with MFS75–140A models manufactured since 2025.

The diagnostic tool kits for MFS40-60A can be used without modification.



Interchange-ability	A		B		C		D		● — ● Interchangeable as a set
	Part	Engine	Part	Engine	Part	Engine	Part	Engine	
	Old → New	Old → New	Old → Old	Old → Old	Old → Old	Old → Old	Old → Old	Old → Old	